Inspection Services



| Plumbing | |
|--|--|
| A NPNI M D S | |
| 1. Service Line: Copper 2. Main Water Shutoff: Basement 3. Water Lines: Copper 4. Drain/Vent Pipes: PVC, Cast iron | |
| 5. Gas Service Lines: Black pipe. | |
| Basement Water Heater 6. Water Heater Operation: Functional at time of inspection 7. Type: Natural gas Capacity: 50 Gal. 8. Approximate Age: 3 yrs. Area Served: Entire house 9. Flue Pipe: Single wall - Flue pipe slopes downhill. Repairs are recommended for safety. | |
| 10. DDDDDDDDDDDDDDDDDDDDDDDDDDDDDDDDDDDD | |
| | |
| Basement and Foundation ANPNIMDS | |
| Main Basement — | |
| Construction Type Masonry Construction Type Masonry Styrofoam insulation exposed at some walls this is normally to be covered with drywall for safety. | |
| Basement walls are mostly finished, this limited the inspection. | |
| 3. Support Beams: Steel I-Beam 4. Support Columns: Steel Posts 5. Support Support Columns: Steel Posts 6. Floor/Slab: Concrete | |

Inspection Services



| | Attic (Contin | ued) Electrical: Not Visible |
|---|---|---|
| | Interior Com | nmon Rooms ws are tested that are accessible at time of inspection. |
| | A NPNI M D S | |
| > | All interior finished 1. X C C C C C C C C C C C C C C C C C C | common rooms Living Space Walls / Ceilings Finished Floors: Wood Doors: Hollow core - Lock set not working @ lower bath. |
| | 4. | Windows: Wood casement, Wood slider - Multiple window cranks stripped out, those windows not tested. |
| | | Softness noted @ sash of East dining room window, recommend further evaluation by a qualified contractor. |
| | | Defective thermal seal, @ lower SE window. |
| | | Note: Loose weather stripping noted @ lower NE window. |
| | | Note: Windows are original casement windows. These windows need to be kept sealed and painted. Some wood rot may occur inside the sash and is not always visible at a home inspection. All operable windows were opened and inspected at this time. |
| | 5. X X X X X X X X X X X X X X X X X X X | Electrical: 110 VAC Stairs / Railings Heat / Cool Source: |
| | 8. | Smoke Detector: Hard wired smoke detectors, these detectors have battery backups and batteries need to be changed periodically. Smoke detectors do not appears to be working properly, recommend repair/replacement. |
| | | No carbon monoxide detectors located, 1 is required per habitable level. |